

# Numerical Evaluation Criteria

	Outstanding .9 - 1.0	Above Average .7 - .8	Average .5 - .6	Below Average .3 - .4	Unsatisfactory 0 - .2
C L E A N L I N E S S	<p><b>Over 90% of the spaces inspected:</b></p> <p>Were clean.</p> <p>It was evident that assigned personnel took pride in their spaces.</p> <p>Spaces shined.</p>	<p><b>80 - 89 % of the spaces inspected:</b></p> <p>Were clean.</p> <p>No trash visible.</p> <p>Tools and gear were properly secured.</p> <p>No trash beneath and behind cabinets.</p>	<p><b>70 - 79 % of the spaces inspected:</b></p> <p>Were clean.</p> <p>Nothing out of the ordinary stood out.</p>	<p><b>60 - 69% of the spaces inspected:</b></p> <p>Were clean; <i>however</i>, most of the spaces had trash that had not been titivated for some time.</p> <p>Loose gear and trash were not secured.</p> <p>Areas underneath and behind cabinets had not been cleaned for some time.</p>	<p><b>At least 40% (1 - 60%) of the spaces inspected:</b></p> <p>Were dirty.</p> <p>Most of the spaces contained trash.</p> <p>Loose gear and trash were not secured.</p> <p>Areas underneath and behind cabinets appeared not to have been cleaned since the ship was built.</p>
P R E S E R V A T I O N	<p><b>Over 90% of the spaces inspected:</b></p> <p>Had no major exfoliation, were properly maintained and well preserved.</p> <p>It was evident that assigned personnel took pride in their spaces.</p> <p>Spaces shined.</p>	<p><b>75 - 89% of the spaces inspected:</b></p> <p>Had no major exfoliation and were properly maintained and well preserved.</p> <p>Personnel assigned to the space had a maintenance plan to address areas requiring work.</p>	<p><b>60 - 74 % of the spaces inspected:</b></p> <p>Had no major exfoliation.</p> <p>Nothing out of the ordinary stood out.</p>	<p><b>50 - 59% of the spaces inspected:</b></p> <p>Had no exfoliation; <i>however</i>, most of the spaces had rust.</p> <p>Personnel assigned to the space did not have a maintenance plan to address areas requiring work.</p>	<p><b>At least 50% of the spaces inspected:</b></p> <p>Had exfoliation and some form of rust build-up.</p> <p>It was clear that no one had a maintenance plan to address areas requiring work</p>
S T O W A G E	<p><b>In over 90% of the spaces inspected:</b></p> <p>Equipment and materials were very well stored.</p> <p>It was evident that assigned personnel took pride in their spaces.</p>	<p><b>In 80 - 89% of the spaces inspected:</b></p> <p>Equipment and materials were well stored.</p> <p>No loose gear adrift in 80 - 90 % of the spaces inspected.</p> <p>Tools and gear were properly secured.</p>	<p><b>In 70 - 79 % of the spaces inspected:</b></p> <p>Equipment and materials were properly stored.</p> <p>Nothing out of the ordinary stood out.</p>	<p><b>In 60 - 69% of the spaces inspected equipment and materials were stored; <i>however</i>, most of the spaces had gear adrift and were not properly secured for sea.</b></p>	<p><b>At least 40% (1 - 60%) of the spaces inspected contained gear adrift/not secured with potential of either equipment damage or personnel safety hazzard.</b></p>
M a t e r i a l  C o n d i t i o n	<p><b>In over 90% of the spaces inspected:</b></p> <p>Equipment and materials were very well maintained.</p> <p>It was evident that assigned personnel took pride in their spaces.</p>	<p><b>In 80 - 89 % of the spaces inspected:</b></p> <p>Equipment and materials were well maintained.</p> <p>No excessive out of commission equipment</p> <p>The material condition of tools and equipment were satisfactory.</p>	<p><b>In 70 - 79 % of the spaces inspected:</b></p> <p>Equipment and materials were properly maintained.</p> <p>Nothing out of the ordinary stood out.</p>	<p><b>In 60 - 69% of the spaces inspected equipment and materials were properly maintained; <i>however</i>, most of the spaces indicated need for some form of maintenance and/or preservation.</b></p>	<p><b>In at least 40% (1 -.6) of the spaces inspected material condition of the space and/or equipment required maintenance with potential of either equipment damage or personnel safety hazzard.</b></p>